

User Guide

Auto Lensmeter ALM 700



Introduction

This device is aims to measure S, C, A, prism refractive power, UV transmission and PD of the framed lens and contact lens.


About This Manual

Please read this manual thoroughly so that safe and effective operation is ensured.

- (1) The information contained in this manual is subject to change without notice.
- (2) While reasonable efforts have been made in the preparation of this document to ensure its accuracy, you should contact your local distributor immediately if any queries arise due to editorial errors or omissions etc.
- (3) If finding any imperfect collating or missing pages, contact your local distributor for replacement.

This manual contains important contents to prevent users or others from harms and to use this device safely.

Read this manual after understanding the symbols below and follow the instructions in use.

 Warning	This symbol indicates that mishandling as a result of failure to comply with the indications can result in “personal death” or “serious injury”.
	Denote general ban or prohibition.
	General mandatory action.
 NOTE	Additional information which is important to the text or useful/ convenient to know.
	The number on the left is the lower limit and the one on the right is the upper limit of the temperature.
	The number on the left is the lower limit and the one on the right is the upper limit of the humidity.
	Avoid direct sunlight.







	<p>this product complies with applicable CE directives.</p>
	<p>Manufacturer</p>
	<p>Electrical and Electronical Waste – please contact your distributor to recycle this product</p>

 This manual contains the information about basic operation, inspection and maintenance etc. of ALM700.

Safety Consideration

General Cautions

- It affects its measurement accuracy if fingerprints or dust etc. are on the optical components such as glass parts under the lens stand.
Do not touch them with hands, and avoid dust.
- If fingerprints or dust are adhered on the optical parts such as a lens etc., wipe it gently with a soft cloth.
- Observe the following environmental conditions for use, storage and transportation.

Use		
Storage		
Transportation		




- Avoid installation near TV or radio. The reception can be disturbed by electrical noise.
- If liquid is spilled on this device or a foreign substance is entered in it, unplug the power cord and contact your local distributor.
- Turn off the power immediately and contact your local distributor if malfunction (noise, smoke etc.) occurs. It can result in fire or injury if you keep using it.
- Do not attempt to disassemble it. It can result in malfunction or fire.
- If malfunction occurs, do not touch the inside of this device. Unplug the power cord and contact your local distributor.
- In case of disposal, comply with the regulations and recycle plan of the local government. Inappropriate disposal causes a negative effect on environment.

Contents


Introduction.....	1
About This Manual	1
Safety Consideration.....	3
1. Accessories.....	6
2. Device.....	7
2.1 General Description of Device.....	7
2.2 Parts Identification.....	7
3. Instructions for Use.....	9
3.1 Installation.....	9
3.2 Connection/ Wiring.....	10
3.3 Maintenance/ Inspection	10
3.4 Disposal.....	11
4. Measurement Screen.....	12
4.1 Description of Measurement Screen.....	12
4.2 Preparation for Measurement.....	13
4.2.1 Device Setting	13
4.2.2 Setup (Device Setting) Screen	13
4.2.3 ID Screen	15
4.2.4 Data Output Screen	16
4.2.5 Data/Time Screen.....	17
4.2.6 Default Setting Screen.....	17
5. Operating Instructions of Device.....	18
5.1 Lens Holder.....	18
5.2 Lens Plate	18
5.3 Marking Lever	19
5.3.1 Operating Instructions.....	19
5.3.2 Replacement of Marking Pen	20
5.4 Printer.....	21
5.4.1 Operating Instructions.....	21
5.4.2 Installation and Replacement of Printer Paper.....	22
5.5 Replacement of Fuse.....	23
6. Measurement.....	24
6.1 Checkup before Measurement	24
6.2 Measurement of Single Lens.....	25
6.3 Measurement of Framed Lens	26
6.4 Pupillary Distance (PD) Measurement.....	27
6.4.1 Device Setting	27
6.4.2 Measurement Procedure.....	27
6.5 Measurement of Multifocal Lens	28
6.6 Measurement of Progressive Lens.....	29
6.7 Measurement of Ultraviolet (UV) Transmission.....	32
6.7.1 Device Setting	32
6.7.2 Measurement of UV Transmission after Measuring Degree.....	32
6.8 Measurement of Contact Lens	33
6.8.1 Preparation.....	33

6.8.2 Measurement Procedure.....	33
7. Marking	34
7.1 Lens without Astigmatism.....	34
7.2 Lens with Astigmatism	34
7.3 Marking of Prism Lens.....	35
8. Other Functions	36
8.1 Auto Memory Function.....	36
8.1.1 Operation Procedure	36
8.2 Power Saving Function	37
9. Error Display.....	38
9.1 Type.....	38
9.2 Error Handling Procedure.....	39
10. Storage of Device	40
11. Specification.....	41
12. EMC (Electromagnetic compatibility)	42


1. Accessories




Power cord: 1
(2.5m)




Printer paper: 1
(Width: 58mm)



Operation manual: 1



Dust cover: 1



Contact lens stand: 1



Use the accessories specified by us.



The printer paper is the thermal paper roll.

Avoid direct sunlight, high humidity and high temperature at the time of storage.

2. Device


2.1 General Description of Device

This device aims to take the measurements of SPH, CYL, AXIS, prism refractive power and optical axis coordinate of unprocessed lens, processed framed lens and contact lens, and to put dots on them to find its axis.

As an external feature, the angle of the LCD can be changed.

Refer to “3. Instructions for Use” about the operating precautions of this device.

2.2 Parts Identification



LCD

Color LCD with 640 X 480 dots

User-friendly LCD which is adjustable vertically within operating range (60°)

Touch panel is adopted.

Pilot lamp

Lamp to indicate ON (light on)/ OFF (light off) and power saving mode (blink)

Marking lever/ lens holder

The marking lever and lens holder are integrated.

•Marking lever: puts the dots by pressing the lever down.

•Lens holder: fixes the framed glass on the lens stand by moving the lever up and down.

Lens stand

Take a measurement by placing the framed lens on the lens stand.

Lens plate

The plate to be reference of the cylindrical axis and specified direction of the prism.

For the framed lens, take a measurement so as that the lens frame contacts with the lens plate.

Lens plate lever

Moves the lens plate back and forth

Nose pad

Used for measuring PD of the framed lens.

Set the framed lens so as that the nose pad is placed on it. The judgment of right and left and PD measurement are performed based on the position of the nose pad.

Memory/Add switch

The switch to store the measurement values on the measurement screen of single focus lens, multifocal lens and contact lens.

Freezes the display of the measurement values and store them.

The switch to execute the near and far points in case of manual measurement on the progressive lens measurement screen

Communication connector

The communication connector to transfer the measurement data to the other devices and computers.

Power inlet

The inlet to connect the power cord supplied to supply power.

Power supply switch

The switch to turn on/ off the power of the device

Printer


Prints out the measurement values

3. Instructions for Use

3.1 Installation

- (1) Do not expose the device to sunlight or bright light from lighting equipments.

 NOTE Take extra caution to avoid strong light because it may cause the failure of measurement.




Do not install the device in places where either dust or rubbish may accumulate.

Also, the environments with extremes in heat and humidity should be avoided.

In case of using the device, ensure to comply with the environmental conditions of unpacking and usage before starting a measurement.

- Temperature range for use: 5°C to 40°C
- Humidity range for use: 30%HR to 95%HR
- Temperature range for storage: -10°C to 55°C (No dew condensation)
- Humidity range for storage: 10%HR to 95%HR (No dew condensation)



- (2) Keep away from inflammable or explosive gases as well as storage area of the medical supplies and chemicals.

- (3) Keep away from the sites that experience strong vibrations or sudden shocks.
- (4) The device might be broken if it falls down. Also, it might cause injury if dropping it. Therefore, do not store it at an unstable place or in high, 'out of reach' place.




- (5) Keep this device away from water (liquid).
 - Degree of protection: IP20

3.2 Connection/ Wiring

- (1) The earth cable of the power cord should be connected to the earth terminal.
- (2) Avoid damaging the power cord (such as bending it in an extremely small size, pulling, placing a heavy object on it etc.). Also, do not fabricate the cord.
- (3) When the power cord is damaged, (breaks, damage of cover etc.), replace it to the new one. Fire or electric shock may occur if you keep using it.
- (4) Insert the power cord firmly into the outlet and device. If not, fire or electric shock may occur.
- (5) Keep the power cord clean without any dust or oil etc. on it. The dirty terminal may cause malfunction or fire.
- (6) When the power cord gets hot after use, check for the dirt of the terminal unit. If you find no dirt, replace the power cord to the new one. Fire or electric shock may occur if you keep using it.
- (7) Use it with the correct power-supply voltage. Fire or electric shock may occur if using it with more than the rated supply voltage.
- (8) Always hold the plug when plugging or unplugging the power cord.
- (9) Do not touch the plug with wet hands. You may get an electric shock.
- (10) If the device is not used for a long time, unplug the power cord from the outlet.

3.3 Maintenance/ Inspection

- (1) This is the precision optical device. Make sure not to mishandle or drop it.
- (2) **Do not touch** or allow dust to adhere on the optical parts (i.e. lenses), as the measurement accuracy could be adversely affected by fingerprints and dust etc.




When fingerprints or dust are adhered onto the optical parts, gently wipe them with the accompanying dust cloth or a soft cloth. In this instance, make sure not to scratch them.

- (3) If the main unit cover or operation panel is dirty, gently wipe it with a dry cloth. For hard to remove stains, a damp cloth or neutral cleanser is recommended.

 Avoid using organic solvent such as thinner which may damage the water based paint finish or device.

- (4) If the device is not used for any length of time, unplug the power cord.
When the device is not in use, protect it with the accompanying dustproof cover. The measurement accuracy could be affected by dust.



- (5) Never attempt to fix or remodel the device. When the device fails to function properly, **do not touch the inside**. Contact us or your local distributor.

3.4 Disposal

In case of disposal, comply with the regulations and recycle plan of the local government. Inappropriate disposal causes a negative effect on environment.

4. Measurement Screen

4.1 Description of Measurement Screen



Measurement screen of single focus lens, multifocal lens and contact lens

※ The display of the measurement screen reflects the setting and condition of the device.

The touch panel is adopted. They are corresponding to the icons on the monitor.

【Explanation about switches】

Name of icon	Icon	Description of function
Bottom of monitor: 5		
Device setting		Switch to the Setup (device setting) screen.
Switch of measurement		Switches to multifocal lens measurement from single focus lens.
Unprocessed lens/ framed lens selection switch		Selects unprocessed, left or right lens.
Clear		Deletes measurement values stored in memory.
Measurement value output		Prints out measurement result, outputs data from RS232C or both.
Lens stand unit: 1		
Memory/Add switch	No icon	Stores measurement values in memory and take a measurement of ADD.

4.2 Preparation for Measurement

4.2.1 Device Setting

This device is ready for use with the standard mode but the setting can be changed easily as needed.

Switch to the Setup (setup of device) screen by touching  at the bottom of screen.

Change of switch function

The functions of each switch are changed on the menu screen. The icons are displayed on the screen. Touch the icon in accordance with the display.

NOTE

: Moves the cursor downward at each setting item

: Moves the cursor upward at each setting item

: Goes to a further page of Setup. ( →  →  → )

: Selects the item of each setting item. The selection cursor moves vertically.

: Switches back to the measurement screen.


4.2.2 Setup (Device Setting) Screen

[1/4 screen]




Item	Description of Function
Cyl	Selects sign for Cyl: - / + / ±
Step	Selects step to display measurement value 0.25 / 0.12 / 0.01
Auto Prog.	Sets auto detection of progressive lens On / Off
Lens	Selects lens to be measured Normal : Framed lens H CL : Hard contact lens S CL : Soft contact lens
Auto Memory	Sets auto memory at the time of "Marking OK" On / Off
ADD Measure	Selects auto/ manual memory of far and near points F/N.AT : Stores both near and far points automatically N.AT : Stores only near point automatically Manual : Stores data manually
PD Measure	Selects if performing PD measurement or not On: Perform / Off: Not perform

【2/4 screen】




Item	Description of Function
UV Measure	Selects if performing UV transmission measurement or not
	On: Perform / Off: Not perform
UV Graph	Selects if displaying UV transmission graph or not (displayed only on the progressive lens measurement screen)
	On: Perform / Off: Not perform
Prog. Graph	Selects if displaying the assessment graph or not
	On: Display / Not display
Graph Print	Selects if printing out the assessment graph after measuring progressive lens
	On: Print out / Off: Not print out
Prism	Selects if displaying prism or not, and selects the unit to be displayed
	Off: Not display X-Y: X-Y display P-B: Prism value – base direction
	Select if displaying prism value of X-Y direction in mm
Prism (mm)	Select if displaying prism value of X-Y direction in mm
	On: Display / Off: Not display
Abbe	Selects Abbe number : 20 / 30 / 40 / 50 / 60

【3/4 screen】



Item	Description of Function
Ray	Selects measurement wavelength
	e-line / d-line
Standby	Selects time to activate standby mode
	Off / 3 min. / 5min. / 10min.
Language	Selects language displayed on screen
	English, French, Spanish, Italian, Portuguese, German, Chinese
Brightness	Sets brightness of screen (50% to 100%)
Sound Mute	Sets On/ Off of buzzer at the time of operating switches
ID	Switches to ID screen
Data Output	Switches to Data Output screen

【4/4 screen】




Item	Description of Function
Date/Time	Switches to Date/Time screen
Default Setting	Displays the Setup items changed from default and changes the setting back to the default by pressing  .

4.2.3 ID Screen

This screen is to create the data for printing out the distributor's name or message on the printout.

(1)



The cursor in  moves by pressing the arrows.

(2) While Memory/Add switch is held



The cursor in  moves while the Memory/ADD switch is held

The screen shown on the left appears by selecting "ID Screen".

(1) is the screen for writing the information.
 (2) is the screen for changing or erasing the information.

How to input

In the Screen (1), select the characters with    and enter them with . Any changes made will overwrite the original characters.

The maximum number of characters is 44 (22 characters X 2 lines).

In case of changing the characters, move the cursor to the one changed by pressing    with holding the Memory/Add switch. Return to Screen (1) and select the character to be input with    and press .

How to delete

In case of deleting the characters, move the cursor to the one deleted with    and press .

4.2.4 Data Output Screen

This screen is to set the communication parameter for outputting the measurement values to the externally-connected PC etc.


The measurement values and data created on the “ID Screen” are output by selecting “RS232C” or “Both” of “Data Output” on the Setup screen.

 **NOTE** The output content is same with the one of the printout.
However, the graph at the time of progressive lens measurement is not output.

Communication setting to PC etc.


The communication from RS232C port is set on “Data Output”.

【Setting screen in case of outputting from RS232C】



Item	Description		
Output Device	Setting of output destination		
	Print	RS232C	Both
	Device printer	RS232C terminal	Both
Display on measurement screen			
Auto Comm	Setting		
	“Off”		“On”
	Output by touching the measurement screen output icon		Measurement values are output continuously
Band Rate (communication speed)	Select from 115200, 38400 or 9600.		

 **NOTE** In case of output from RS232C, the data is output only in English regardless of language setting.



Use the straight cable (D-sub 9 pin: male/ D-sub 9: female) as the connection cable at the time of outputting the measurement values by using the RS232C.


※ Contact your local distributor if you have anything unclear or any questions regarding operation and connection.

 **NOTE** Use a shield wire for a connecting cable to protect the output data from noise.

4.2.5 Data/Time Screen

The screen to set the date and time for printout and communication output

(1)



Select the item to be changed with

and set the detail with .


“Date Form”: YMD → Year, Month, Day

“Date Form”: DMY → Day, Month, Year

“Date Form”: MDY → Month, Day, Year

The setting can be also changed by touching the screen.

(2) While Memory/Add is pressed



Date: change of date

Select “Date” with .

Move the cursor to the item to be changed with

.

While the Memory/Add switch is held, the Screen (2) is displayed. Make changes with

.

Time: change of time

Select “Time” with .

Move the cursor to the item to be changed with

.

While Memory/Add switch is pressed, the Screen (2) is displayed. Make changes with

.

4.2.6 Default Setting Screen

The screen to change the setting of the device back to the default




Touch Press if you wish to change the setting back to the default.

Press if you do not wish to change the setting back to the default. It goes back to the measurement screen by selecting it.

5. Operating Instructions of Device

5.1 Lens Holder

- (1) Raise the lever to the operational direction until it is unlocked.
- (2) Lower the lens holder slowly and fix the lens.




 Do not give strong impact to a lens when lowering the lens holder.
When rising the lens holder, make sure to move to the top.

5.2 Lens Plate

The lens plate is the reference of the cylindrical axis.

Place the framed lens and rotate the lens plate lever to the direction of the arrow so that the bottom of the lens touches the lens plate. After that, lower the lens holder and fix the lens.



5.3 Marking Lever

5.3.1 Operating Instructions

(1) Turn and lower the marking lever.





(2) Place the tips of the marking pens on the lens surface softly.

 Do not mark several times at the same point.
The marking pen may be worn out quickly.

(3) Release the finger after marking.

(4) The marking lever returns to the initial position.

Marking lever



 Avoid the followings since they may damage the tips of the marking pens.


- Perform marking roughly
- Operate the marking lever without a lens set.
- Touch a tip of the marking pen during cleaning.

5.3.2 Replacement of Marking Pen


The marking pen is the consumable item.

Replace it if the imprint becomes thin or the pen tip is worn.

(1) Remove the marking pen by pressing and rotating it 90 degrees as shown below.



(2) Insert the new pen back to the initial position as shown below.



- Ensure to use the marking pen specified for “ALM700”.
- Do not touch the pen tip at the time of replacement.

5.4 Printer

5.4.1 Operating Instructions

The measurement values can be printed out by touching  after taking a measurements.

Add measurement values are displayed only at the time of measurements of multifocal lens and progressive lens (Left: ADD1, Right: ADD2)

The unit of the prism value is different according to the setting.

PD of right eye

UV transmission of right eye

PD (PD of right eye and left eye)

2013 12 13 15:40

Name

<R>

S : +1.75
C : -0.75
A : 90

ADD: +0.75 +1.00

P : 0.00 0 B

PD : 30.0

UV : 0%

F V N V

<L>

S : +2.00
C : -0.50
A : 90

ADD: +1.00 +1.25

P : 0.00 0 B

PD : 30.0

UV : 0%

F V N V

<R+L>

PD : 60.0

ESSILOR ALM700

Distributor's name, comment etc. (printed out only when ID is set)

Number of characters input: 44 characters (22 characters X 2 lines)

Measurement value of right lens

When the assessment graph is printed (when "Graph Print" is set as "On" at the time of progressive lens measurement)

Shown below is the measurement value of the left lens (Same as that for a right lens)

【Printout sample when unprocessed lens is measured】

```

2013 12 13 15:40
Name
<S>
S : +1.75
C : -0.75
A : 90
ADD: +0.75 +1.00
P : 0 0.00 D 1.25
ESSILOR ALM700
    
```

【Printout sample in case of measurement error】


```

2013 12 13 15:40
Name
<R>
S : +1.75
C : -0.75
A : 90
ADD: +0.75 +1.00
P : 0 0.00 D 1.25
<L>
Measurement error
ESSILOR ALM700
    
```

Error display
 Other error displays
 ·SPH Over
 ·CYL Over
 ·Prism Over
 ·Center Error


5.4.2 Installation and Replacement of Printer Paper

(1) Open the printer cover by pressing the printer cover button.




(2) Insert the printer paper with attention to the winding direction.

Note) Insert the printer paper so as that the printer paper comes out from the upside.



- (3) Close the printer cover with the end of the paper taken out a little.
At this time, close it completely until hearing the clicking noise. The error is displayed and the data is not printed out if the cover is opened.



Use the printer paper specified for "ALM700".

5.5 Replacement of Fuse



Warning


Unplug the power cord before removing the fuse holder at the time of replacing the fuse.

Electric shock may occur if removing the fuse holder without

When the fuse is brown out, replace it after removing the fuse holder of the power inlet. The fuse holder is removed from the main unit by pulling it out.




Always use the specified fuse (T2A L 250V).



6. Measurement

6.1 Checkup before Measurement

- The lens holder is set properly.
- The lens under the lens stand is clean.
(In case that the lens is dirty, clean it with a soft cloth.)




Lens stand is removed

- Plug the power cord to the outlet.



Always connect the earth terminal to a ground.

- Set the printer paper in the printer.
(Refer to “5.4.2. Installation and Replacement of Printer Paper”.)
- Confirm that the lens is not placed on the lens stand.
- Turn on the power switch. The screen is displayed in seconds.



Single lens measurement screen


6.2 Measurement of Single Lens

- (1) Place the lens on the lens stand.
Lower the lens holder softly on the lens.
The screen as shown on the right appears.



Do not give strong impact to a lens when lowering the lens holder.
When rising the lens holder, make sure that it is moved to the top and locked.

- (2) Bring the cross cursor to the alignment mark by moving the lens. The message “Alignment OK” appears on the screen when alignment completes. If the lens is the cylindrical one, rotate the lens to fit the axis direction.



The alignment mark represents the optical center of the lensmeter and the cross cursor represents the optical center of the lens.

- (3) Move the lens until the alignment mark and cross cursor overlap. When they overlap, the message “Marking OK” appears to indicate that the marking is ready to be carried out. S, C, A and prism value are stored by pressing the Memory/Add switch. The color of the measurement value area is reversed, and the values are fixed.



- ※ In case of setting “**Auto Memory**” on the Setup screen as “**On**”, the measurement values are stored in memory automatically after the message “Marking OK” appears. In case of deleting the data stored in memory, touch . In case of printing it out, touch .




Memory/Add switch



6.3 Measurement of Framed Lens

(1) Place the framed lens on the lens stand and lower the lens holder softly on the lens. Move the lens plate to the near side with the lens plate lever so that the bottom of the lens touches the lens plate.



(2) Specify the right or left of the framed lens by touching . The icon in the upper right corner of the screen switches to .



(3) Perform alignment so as that the bottom of the framed lens always touches the lens plate in a manner similar to the single lens.



(4) Save the measurement values in memory by pressing the Memory/Add switch after measurement. The color of the measurement value area is changed, and the measurement values are fixed.

 **NOTE** In case of setting “Auto Memory” on the Setup screen as “On”, the measurement values are automatically stored in memory after the message “Marking OK” appears.

(5) Switch the lens from right to left and place the lens in a manner similar to (1). Switch the measurement to the left lens by touching . At this time, the measurement values of the right lens remain on the screen. In case of measuring PD with the setting of PD Measure On, the right eye and left eye are switched automatically.



 **NOTE** The measurement of the lens can be started from either right or left. In case that the measurement values of both right and left are stored, the values on the selected side are deleted by touching .

6.4 Pupillary Distance (PD) Measurement

6.4.1 Device Setting


On the setup screen, confirm that “PD Measure” is set as “On”, and the lens measurement is set for both of right and left lens.

※ In case that “PD Measure” is “Off”, the PD measurement value and measurement area are not displayed.


6.4.2 Measurement Procedure (Right lens ⇒ Left lens)

- (1) Pull the lens plate toward the examiner.
- (2) Place the framed lens so as that the bottom of the frame contacts with the lens plate with the frame contacting with the **left nose pad**. Place the **right lens** on the lens stand and hold it with the lens holder softly.
- (3) Achieve an alignment by moving the right lens back and forth, and right and left with the frame always contacting with the lens plate. Store the measurement values and PD measurement values of the right lens by pressing the Memory/ Add switch after completing alignment.
- (4) After the measurement of right lens, place the **left lens** on the lens stand with the frame contacting with the **right nose pad**, and hold the lens with the lens holder softly. At this time, it is switched from right lens to left lens automatically based on the position of the nose pad.
- (5) In a manner similar to (3), achieve an alignment of the left lens. After completing alignment, store the measurement value of the right lens and PD measurement values by pressing the Memory/ Add switch.

Measurement of right lens



Measurement of left lens



NOTE

In case that “Auto Memory” on the setup screen is set as “On”, the measurement values are stored automatically after the message “Marking OK” is displayed.

Measurement screen

The screenshot shows a measurement screen with the following data:

S	+3.00	S	+3.00
C	0.00	C	0.00
A	0	A	0
Px	0 0.00	Px	I 0.00
Py	U 0.00	Py	U 0.00

At the bottom, the PD values are displayed:


- PDL 32.5 (Left PD measurement value)
- PD(R+L) : 65.0 (Right and left PD measurement values)
- PDR 32.5 (Right PD measurement value)

6.5 Measurement of Multifocal Lens

- (1) Place the lens on the lens stand and hold it with the lens holder softly.
- (2) Take a measurement of far point, and press the Memory/ Add switch. SPH, CYL, AX and prism values are stored. The measurement result stored is fixed, and color of the measurement value display area changes. “Ad1” is added by pressing the Memory/ Add switch one more time.
- (3) Perform the measurement of near point after confirming that “Ad1” is displayed. Move the lens so as that the near point (near-sight segment) comes to the center of the lens stand.



 A measurement can be taken even if the messages of “Alignment OK” and “Marking OK” are not displayed.



- (4) Store the ADD value of the near point (near-sight segment) in memory by pressing the Memory/Add switch. The color of the Ad value is reversed after storing it.



Display of ADD value

In case of trifocal lens, display “Ad2” by pressing the Memory/Add switch one more time. After that, repeat (3) and (4) after bringing the second near point (near-sight segment) to the center of the lens stand.

Refer to “6.3. Measurement of Framed Lens ”

6.6 Measurement of Progressive Lens

- (1) Take a measurement of progressive lens.
Set “Auto Prog. ” and “ADD Measure”.

Auto Prog.

Off :No auto judgment for a progressive lens

On :Auto judgment for a progressive lens

ADD Measure


F/N.AT :Auto memory of far and near points

N.AT :Auto memory of near point

Manual :Manual memory of far and near points



- (2) Switching to progressive lens measurement screen
The icon is changed to , and the progressive lens measurement screen is displayed by pressing  (single/ progressive lens selection switch).



NOTE

In case that **Auto Prog** is set as “On”, the lens is automatically judged whether the lens is a progressive lens or not.

Set the lens in the center region of the progressive zone. It starts the auto judgment of the progressive lens. When the lens is identified as a progressive lens, the screen is switched to the progressive lens measurement screen. If not, the measurement screen remains as the single focus lens measurement screen.

When the ADD value is small (less than 1D), the auto detection may not be performed. Also, if the progressive zone cannot be found at where the lens is set, the auto detection may not be performed.

In these cases, move the lens back and forth, and right and left slowly.

When the ADD value is small (less than 1D), the framed lens is small, or the lens is dirty or has some flaws, the far point and near point may not be detected automatically. In such case, take a measurement manually.

(3) Measuring procedure of progressive lens (when N.AT is selected for ADD Measure)

1) Detection of progressive zone

First, find the progressive zone by moving the lens back and forth, and right and left **slowly**.

The cross cursor (screen shown below) appears when the progressive zone is found.



NOTE


Press the Memory/Add switch in case that the progressive zone cannot be detected because ADD value is small etc. It switches to the measurement screen of the far point.

2) Measurement of far point

Take a measurement of far point. Move the lens toward the device so as that the center of the alignment mark overlaps with the cross cursor.

The color of the cross cursor is changed to blue by pressing the Memory/Add switch after they overlaps.

At this time, the measurement values of the far point are stored.




NOTE

When “ADD Measure” on the Setup screen is set as “F/N.AT”, it is detected automatically and the measurement values are stored in memory.

3) Measurement of near point


Take a measurement of near point. As shown on the right, move the lens **slowly** to move the cross cursor (red)

according to ▲. If it goes out of the progressive zone, the cross cursor moves right or left. If it goes out of the progressive zone, bring it back to the zone and move the lens toward near point.



NOTE

The cross cursor on the screen indicates the actual measurement position on the lens. For example, if it goes to the right side of the lens which is out of the progressive zone at the time of moving from far point to near point, the cross cursor is displayed on the right deviated from the progressive zone.




Perform the alignment carefully when it comes closer to the near point and ▲ starts blinking. Once the near point is detected, it blips. The cross cursor is fixed at the near point and its color changes to blue. When the near point is attained, the ADD value is stored in memory automatically.

※Another ADD value (Ad2) can be stored in memory anywhere by pressing the Memory/Add switch after measurement.

The progressive judgment screen appears again by setting

the lens for the left eye and touch  after completing the measurement. Take a measurement of the left lens in the same manner as right lens.

※Measurement can be started from either right or left lens.



(4) Display of ADD value and assessment graph, and manual operation
 (when “Manual” of “ADD Measure” is selected)


When setting “Prog. Graph” as “On” on the Setup screen, the graph is displayed on the progress lens measurement screen.

Depending on the type of lens, it may be difficult to detect each point automatically even though normally the near and far points are detected automatically. In such case, take a measurement manually by reference to the ADD value and assessment graph.


To take a measurement of far point manually, carry out the alignment in the same manner as the auto measurement.

For the measurement of near point, press the Memory/Add switch where the ADD value is the highest while the alignment cursor stays in the progressive area.

The near point is where the assessment line moves closer to the Y coordinate. Therefore, carry out alignment by reference to the shape of the graph and blinking of ▲.



【Framed lens: reference】



6.7 Measurement of Ultraviolet (UV) Transmission

Checks the UV protection function by taking a measurement of the UV transmission of lens. The light wavelength for UV transmittance measurement is 375 nm. This does not measure the transmittance of a whole area of UV light.

6.7.1 Device Setting



- Confirm that “UV Measure” is set as “On” before the measurement of UV transmission.
- ※ In case of setting “UV Measure” as “Off”, neither UV transmission nor UV transmission display area is displayed.
- If displaying UV transmission graph, set “UV Graph” as “On”.
- ※ The graph is displayed only in the progressive lens measurement mode.
(Refer to 4.2.1. Device Setting.)

6.7.2 Measurement of UV Transmission after Measuring Degree

The UV transmission measurement is performed after achieving an alignment of the lens and pressing the “Memory/Add switch” to store the measurement values.

 **NOTE** At the time of progressive lens measurement, the UV transmission measurement is performed **after taking a measurement of far point.**

- In case of taking a measurement again, clear the measurement values first by touching .
- ※The values are cleared in order of degree of lens and UV transmission.



6.8 Measurement of Contact Lens


6.8.1 Preparation

- (1) In case of taking a measurement of hard contact lens, select “H CL” on Setup screen. In case of taking a measurement of soft contact lens, select “S CL” on Setup screen.
- (2) Change the lens stand to the accompanying contact lens stand.



6.8.2 Measurement Procedure


- (1) Set the contact lens on the contact lens stand as shown below.



NOTE

Remove the water or moisture from the lens, and set it on the stand with paying attention not to distort it. Then, take a measurement quickly. A bifocal contact lens cannot be measured.

- (2) Replace the standard lens stand with the contact lens stand.



- (3) Lower the lens holder, and hold the contact lens stand which the contact lens is already placed.

7. Marking

Refer to “5.3. Marking Lever.”

7.1 Lens without Astigmatism

- (1) Overlap the cross cursor with the alignment mark on the screen by moving the lens.
You are ready for marking when the message “Marking OK” is displayed.
- (2) Lower the marking lever to mark on the lens.



7.2 Lens with Astigmatism

- Marking according to the axis in the prescription
 - (1) Move the lens so as that the axis mark aligned with the angle in the prescription approximately.
 - (2) To be more precise, align it according to the axis value indicated.
- Marking on the cylindrical axis
 - (1) Move the lens so as that the axis mark aligned with 0° approximately.
 - (2) To be more precise, align it so as that the axis value indicated becomes 0°.



7.3 Marking of Prism Lens

- In case that prescription is expressed in X-Y

- (1) Select “X-Y” from “Prism” on the “Setup” screen.
- (2) Move the lens so that the prism values displayed on the screen match with the ones on the prescription.

The meanings of the prism values displayed are as shown below.

Px	I	Base In	(base inward)
Px	O	Base Out	(base outward)
Py	U	Base Up	(base upward)
Py	D	Base Down	(base downward)



- In case that prescription is expressed in P-B

- (1) Select “P-B” from “Prism” on the “Setup” screen.
- (2) Move the lens so that the prism values displayed on the screen match with the ones in the prescription.


P: Prism value
B: Base direction



- In case that prescription is expressed in mm

- (1) Set “Prism (mm)” as “On” on the “Setup” screen.
- (2) Move the lens so that the prism values displayed on the screen match with the ones in the prescription.

The arrows (↑ ↓ ← →) indicate the direction of the measuring position on the lens from its optical center.



8. Other Functions

8.1 Auto Memory Function


This device has the function to store the measurement values in memory automatically when the alignment is achieved, and the message “Marking OK” is displayed at the time of the measurements of single focal lens, multifocal lens and contact lens.

8.1.1 Operation Procedure

Move the cursor to “Auto Memory” with  or  and select “On” with .


Return to the measurement switch with  after the settings or changes are completed.

The measurement values are stored in memory automatically when the message “Marking OK” appears after the alignment mark and cross cursor overlap as shown on the right.




8.2 Power Saving Function

The power saving function is activated if no switches are operated or no measurement values are updated with the power on. The switching time to the power saving mode can be set on “Standby” of the Setup screen.



While this function is activated, the power to the measurement light and LCD monitor is turned off.

It returns to the measurement mode by pressing any switch.



9. Error Display

An error message appears when the measurement condition or measurement result is judged as unreasonable. Also, an error message appears when the performance of the device is abnormal.

9.1 Type

※ Display with a three-digit code (number)

Message	Status	Error Detail
Initial Error	Abnormality of device	Any of the measurement values is more than "±0.25". Lens is set on the lens stand. Abnormal measurement because of dust or unnecessary light.
Paper Empty		No printer papers.
Printer Cover Opened		Printer is opened.
Printer Overheated		Printer head is overheated.
EEPROM Failure		Abnormality of memory
Sensor Error		Abnormality of CMOS sensor
※Error * * * (100 -163)		Abnormality of electronic parts
SPH Over	Measurement abnormality	SPH measurement value is more than the upper limit of the measurement range.
CYL Over		CYL measurement value is more than the upper limit of the measurement range.
Prism Over		The prism measurement value is more than the upper limit of the measurement range.
ADD Over		ADD measurement value is more than the upper limit of the measurement range
Measurement Error	Abnormality of image processing	Abnormal light receiving image because of dust, scratch on lens or unnecessary light etc. (The measurement light does not enter into the light receiving sensor normally.)
		Measurement light LED does not light on.
Center Error		Unexpected light receiving image because of unnecessary light.

9.2 Error Handling Procedure

 Warning	Do not disassemble, remodel or repair. It may cause electric shock.
---	--

• Initial Error

This message appears if the lens is placed on the lens stand when the power is turned on or the lens under the lens stand is dirty.

Remove the lens. When the lens under the lens stand is dirty, gently wipe it with a soft cloth. After that, turn the power back on.

(Refer to “6.1 Checkup before Measurement”.) ※

• Paper Empty

This message appears if no papers are set or papers are not set appropriately.

Set the paper appropriately. (Refer to “5.4.2 Installation and Replacement of Printer Paper”.)

• Printer Cover Opened

This message appears when the printer cover is opened. Check the cover and close it properly.

• SPH/CYL/Prism/ADD Over

This message appears in case of measuring the lens which exceeds the upper limit of the measurement range of the device.

Take a measurement of the lens within the measurement range

(Refer to “11. Specification”.)

• Measurement Error or Center Error

This message appears when the direct sunlight or strong glare is on the device, or the lens under the lens stand is extremely dirty or has scratches.

If the lens under the lens stand is extremely dirty, gently wipe it with a soft cloth. Then, turn the power back on.





If an error message other than shown above is displayed or an error message is still displayed even after performing the procedure above, turn off the power, disconnect the power cord and contact your local distributor.

10. Storage of Device

- (1) Points to be checked for long-term storage
 - Turn OFF the power.
 - Remove the power cord from the outlet.
 - Put the dust proof cover on the main unit.
- (2) Notes on storage environment
- (3) Avoid storage under the following conditions
 - Dusty place
 - Where water may get on the device
 - High-temperature and humidity
 - Where sunlight directly contacts
 - Unstable and high place

Observe the environment conditions below for storage.

Environmental condition for storage	
 <p>5°C 40°C</p>	 <p>10% 95%</p>

	<p>Check the above in case that the device is not used or is stored for a long time. When using the device after long-term storage, operate it in accordance with “4.2 Preparation for Measurement”.</p>
---	--

11. Specification

Measurement range	Sphere	-25D to +25D	(0.01/0.12/0.25 step)
	Cylinder	0 to ±10D	(0.01/0.12/0.25 step)
	Axis	0 to 180°	(1°)
	Addition	0 to +10D	(0.01/0.12/0.25 step)
	Prism	0 to 10Δ	(0.01/0.12/0.25 step)
Measurable lens	Unprocessed lens (diameter:100mm) Framed processed lens	} Single lens, multifocal lens, progressive lens	
	Hard contact lens Soft contact lens		} Accompanying lens stand is required
Measurement wavelength	525nm		
UV transmission	0 to 100% (-25D to +25D)		
UV transmission measurement wavelength	375nm (UV-A)		
PD measurement	45 to 85mm (0.5mm step)		
Power Rating	100 to 240V 50/60Hz		
Power Consumption	40VA		
Printer	Thermal printer (paper width 58mm)		
Monitor	Color LCD monitor (5.7 inches)		
Size, weight	170mm(W)×205mm(D)×468mm(H)(400mm: when the monitor is stored) Approx. 4.3kg		
Environmental condition of use	Temperature range: 5□ to 40□		
	Humidity range: 30 to 95%HR (No dew condensation allowed)		

12. EMC (Electromagnetic Compatibility)

This device conforms to the requirements of the EMC (electromagnetic compatibility) standard as shown below.

Guidance and manufacturer's declaration – electromagnetic emissions		
This device is intended for use in the electromagnetic environment specified below. The customer or user of this device should assure that it is used in such an environment.		
Emission test	Compliance	Electromagnetic environment – guidance
RF emissions CISPR11	Group 1	This device is suitable for use in all establishments other than domestic and those directly connected to the public low-voltage power supply network that supplies buildings used for domestic purposes.
RF emissions CISPR11	Class A	
Harmonic emissions IEC 61000-3-2	Class A	
Voltage fluctuations/ flicker emissions IEC 61000-3-3	Complies	

Guidance and manufacture's declaration – electromagnetic immunity			
This device is intended for use in the electromagnetic environment specified below. The customer or user of this device should assure that it is used in such an environment.			
Immunity test	IEC 60601 test level	Compliance level	Electromagnetic environment - guidance
Electrostatic discharge (ESD) IEC 61000-4-2	±6kV contact ±8kV air	±6kV contact ±8kV air	Floors should be wood, concrete or ceramic tile. If floors are covered with synthetic material, the relative humidity should be at least 30%.
Electrical fast transient/ burst IEC 61000-4-4	±2kV for power supply lines ±1kV for input/output lines	±2kV for power supply lines ±1kV for input/output lines	Mains power quality should be that of a typical commercial or hospital environment.
Surge IEC 61000-4-5	±1kV differential mode ±2kV common mode	±1kV differential mode ±2kV common mode	Mains power quality should be that of a typical commercial or hospital environment.
Voltage dips, short interruptions and voltage variations on power supply input lines IEC 61000-4-11	<5 % U_T (>95% dip in U_T) for 0.5cycle 40 % U_T (60% dip in U_T) for 5 cycles 70 % U_T (30% dip in U_T) for 25 cycles <5 % U_T (>95% dip in U_T) for 5s	<5 % U_T (>95% dip in U_T) for 0.5 cycle 40 % U_T (60% dip in U_T) for 5 cycles 70 % U_T (30% dip in U_T) for 25 cycles <5 % U_T (>95% dip in U_T) for 5s	Mains power quality should be that of a typical commercial or hospital environment. If the user of this device requires continued operation during power mains interruptions, it is recommended that this device be powered from an uninterruptible power supply or a battery.
Power frequency (50/60Hz) Magnetic field IEC 61000-4-8	3A/m	0.3A/m	If image distortion occurs, it may be necessary to position the device further from sources of power frequency magnetic fields or to install magnetic shielding. The power frequency magnetic field should be measured in the intended installation location to assure that it is sufficiently low.
NOTE U_T is the a.c. mains voltage prior to application of the test level.			

Guidance and manufacturer's declaration – electromagnetic immunity			
This device is intended for use in the electromagnetic environment specified below. The customer or the user of this device should assure that it is used in such an environment.			
Immunity test	IEC60601 test level	Compliance level	Electromagnetic environment - guidance
Conducted RF IEC 61000-4-6	3 Vrms 150 kHz to 80 MHz	3 Vrms	Portable and mobile RF communications equipment should be used no closer to any part of this device, including cables, than the recommended separation distance calculated from the equation applicable to the frequency of the transmitter. Recommended separation distance $d=1.2\sqrt{P}$
Radiated RF IEC 61000-4-3	3 V/m 80 MHz to 2.5 GHz	3 V/m	$d=1.2\sqrt{P}$ 80 MHz to 800 MHz $d=2.3\sqrt{P}$ 800 MHz to 2.5 GHz where P is the maximum output power rating of the transmitter in watts (W) according to the transmitter manufacturer and d is the recommended separation distance in metres (m). Field strengths from fixed RF transmitters, as determined by an electromagnetic site survey, ^a should be less than the compliance level in each frequency range. ^b Interference may occur in the vicinity of equipment marked with the following symbol: 
NOTE 1 At 80 MHz and 800MHz, the higher frequency range applies.			
NOTE 2 These guidelines may not apply in all situations. Electromagnetic propagation is affected by absorption and reflection from structures, objects and people.			
^a Field strengths from fixe transmitters, such as base stations for radio (cellular/cordless) telephones and land mobile radios, amateur radio, AM and FM radio broadcast and TV broadcast cannot be predicted theoretically with accuracy. To assess the electromagnetic environment due to fixed RF transmitters, an electromagnetic site survey should be considered. If the measured field strength in the location in which this device is used exceeds the applicable RF compliance level above, this device should be observed to verify normal operation. If abnormal performance is observed, additional measures may be necessary, such as re-orienting or relocating this device.			
^b Over the frequency range 150kHz to 80MHz, field strengths should be less than 3 V/m.			
Recommended separation distances between portable and mobile RF communications equipment and this device			
This device is intended for use in an electromagnetic environment in which radiated RF			

disturbances are controlled. The customer or the user of this device can help prevent electromagnetic interference by maintaining a minimum distance between portable and mobile RF communications equipment (transmitters) and this device are recommended below, according to the maximum output power of the communications equipment.

Rated maximum output power of transmitter W	Separation distance according to frequency of transmitter m		
	150kHz to 80MHz $d=1.2\sqrt{P}$	80MHz to 800MHz $d=1.2\sqrt{P}$	800MHz to 2.5GHz $d=2.3\sqrt{P}$
0.01	0.12	0.12	0.23
0.1	0.38	0.38	0.73
1	1.2	1.2	2.3
10	3.8	3.8	7.3
100	12	12	23

For transmitters rated at a maximum output power not listed above, the recommended separation distance d in metres (m) can be estimated using the equation applicable to the frequency of the transmitter, where P is the maximum output power rating of the transmitter in watts (W) according to the transmitter, where P is the maximum output power rating of the transmitter in watts (W) according to the transmitter manufacturer.

NOTE 1 At 80 MHz and 800MHz, the separation distance for the higher frequency range applies.

NOTE 2 These guidelines may not apply in all situations. Electromagnetic propagation is affected by absorption and reflection from structures, objects and people.



ALM700

USER GUIDE (MULTILINGUAL)



Essilor Instruments USA
8600 W. Catalpa Avenue, Suite 703
Chicago, IL 60656
Phone: 855.393.4647
Email: info@essilorinstrumentsusa.com
www.essilorinstrumentsusa.com